

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of)	
)	
Robert Maher et al.)	Group Art Unit: 2116
)	
Application No.: 10/784,702)	Confirmation No.: 1291
Filed: February 23, 2004)	
)	Examiner: Thuan N. Du
Now U.S. Patent No. 7,509,512 B2)	
Issued March 24, 2009)	
)	
For: INSTRUCTION-INITIATED METHOD FOR)	
SUSPENDING OPERATION OF A)	
PIPELINED DATA PROCESSOR)	

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

ELECTRONIC SUBMISSION

**REQUEST FOR CERTIFICATE OF CORRECTION OF
PATENT FOR PTO MISTAKE 37 CFR § 1.322(A)**

Dear Sir:

Pursuant to 37 C.F.R. §1.322(a), hereby request that a Certificate of Correction be issued for U.S. Patent No. 7,509,512 B2. Attached is Form PTO/SB/44 with errors and changes requested.

<u>Error In</u>	<u>Data</u>	<u>Correct Data</u>
Column 2, Line 32	disabling the first clock signal,	disabling the first clock signal[,] .
Column 3, Line 27	...supervision operations a for the computer system...	...supervision operations a for the computer system...
Column 3, Line 31	...BIOS 16 a and logic 18...	...BIOS 16 a and logic 18...
Column 5, Line 47	...disabled. Once, the busy...	...disabled. Once[,] the busy...

Please send the Certificate of Correction to the following:

Mark A. Dalla Valle, Esq.
Vedder Price P.C.
222 N. LaSalle St., Suite 2600
Chicago, Illinois 60601


It is believed there is no fee due. In the event there is a fee, the Commissioner is hereby authorized to charge any additional fees to Deposit Account Number 22-0259.

Dated: April 3, 2009

Respectfully submitted,

VEDDER PRICE P.C.
222 N. LaSalle St., Suite 2600
Chicago, Illinois 60601
telephone: 312-609-7500
facsimile: 312-609-5005

By:



Mark A. Dalla Valle
Registration No. 34,147
Attorney for Assignee

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**

Page 1 of 1

PATENT NO. : 7,509,512 B2
APPLICATION NO. : 10/784,702
ISSUE DATE : March 24, 2009
INVENTOR(S) : Robert Maher et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At Column 2, Line 32,
after "signal" please delete "," and insert -- . -- in its place.

At Column 3, Line 27,
after "supervision operations" please delete "a" .

At Column 3, Line 31,
after "BIOS 16" please delete "a".

At Column 5, Line 47,
after "Once" please delete "," .

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Mark A. Dalla Valle
VEDDER PRICE P.C.
222 North LaSalle Street
Suite 2600
Chicago, Illinois 60606

CHICAGO/#1922289.1